
XG0133K03-A

Product accessories and quantity

Eccentric piece installation steps

Overall partial installation



1. Product accessories and quantity (it is recommended to put more spare screws)

- 1					
The state of the s				OR OR	
4*35 self-tapping screws	4*14 handle screw		small nails	Metal feet	
B3*9 (includes 1 spare)			K20*26 (includes 2 spares)	M24*4	
1 +			OR		
Eccentric rod + eccentric wheel	Built-in door catch	Mediu	m black (gold) color rectangular hand	dle Single hole door iron sheet	
D0*5 (includes 1 spare)	L18*2	J4 ⁷	7(gold)/J49(black)*´	1 L19*2	
	Ed Sala				
Iron partition pin	3.5*12 self-tapping screws		door hinge		
K0*16 (includes 2 spares)	A1*24 (includes 2 spares)		K2*2		
)=()				
breathable hole			screwdriver		
K11*3			1		


Kind tips:

1. When installing, please refer to the drawings to distinguish the boards.

The color of the product is not subject to the instructions;

- 2. Tighten the screws 70%, and then tighten them after everything is completed!
- 3. Some boards have a red side, and the red side faces down or inward.
- 4. Please read all the drawings before proceeding with installation.
- 5. If there are extra screw accessories, they are spare screws provided by the manufacturer!


2. Installation steps of eccentric parts



Screw the eccentric rod to the board

Find the corresponding board and insert it

find round hole



Insert the eccentric wheel into the round hole


Rotate 180° clockwise to lock

the board left and right













Right side panel
















Use A1 to fix M24 everywhere on the pinhole marks on both sides of the No. 5 board.





Small back panel

Knock in the K20 with a tool hammer








<6>




6 Large movable floor


Place plate 6 on the KO







1. Align the KO above the door panel



Completed picture



The installation is complete: